



SAY GOOD-BYE TO LIFT!

The
Ultimate
5-Axis
Solution



Jergens 5-Axis Vises and Quick Change Solutions provide a modular and configurable approach to optimal holding and positioning of components of various sizes and shapes.

5-AXIS VISES

Jergens 5-Axis Self-Centering Vises are engineered to be the ideal solution for low-profile 5-axis workholding.

Quick-change jaws incorporate a pull down feature to actively minimize jaw lift!









ONE STOP SHOPPING!

Ask about our full line of in-stock 5-axis accessories.





Omnitool Industrial Sales 284 Pinebush Rd. Unit #1 Cambridge On N1T 1Z6 Phone: 519-622-3065 email: sales@omnitool.ca www.omnitool.ca

Scan to see Jergens 5-Axis Vises in action!



